



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1765/1

Work Order Type: Weatherization

Audit Name: Audit #20

CLIENT INFORMATION

Client Name:

Address:

Client ID: 18018UE-1765

Alt. Client ID: Carter

AGENCY INFORMATION

Agency: Upper East Tennessee Human Development Agency

Agency Phone:

Address: 301 Louis Street

Fax:

Kingsport, TN 37662

Email Address:

Agency Contact: J.Perryman, David

Work Phone: (423) 608-1143

Cell Phone: (423) 608-1143

Email Address: davidjperryman@yahoo.com

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

1900 Site Built Home 1378 sq. ft. If unvented gas heater is not replaced this job is a walkaway due to unsafe conditions in home.

Auditor--David Perryman

ph#423-608-1143

Lead Certification Needed if 6 sq. ft. of remodeling is done.

No Blower Door due to Oxygen in use in home and unsafe for testing.

Client Name:

Client ID: 18018UE-1765

Alt. Client ID: Carter

Work Order (Bid Form)

Work Order Name: WO/18018UE-1765/1

Report Run On: 11/10/2011

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 5

Measures

Measure 1 DWH Tank Insulation

Components

Inspected

Comment Install to TN. Field Guide Standard

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|-----------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | DHW Tank Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Hot Water Equip | DHW Tank Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 Attic Ins. R-38

Components a1

Inspected

Comment Install Attic insulation 450 sq. ft. of blown in cellulose install R-38 to attic to TN. Field Guide Standard.
Add blown in cellulose to 450 sq. ft. of attic space over first floor roof insulate thru second floor access.

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|--|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | Attic Insulation - Cellulose, Blown - R-38 | SqFt | 450 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Labor | Attic Insulation - Cellulose, Blown - R-38 | SqFt | 450 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 18018UE-1765

Alt. Client ID: Carter

Work Order (Bid Form)

Work Order Name: WO/18018UE-1765/1

Report Run On: 11/10/2011

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 5

Measure 3 DWH Pipe Insulation**Components****Inspected****Comment** Install to TN. Field Guide Standard 6 " from floor for safety to Client.☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|-----------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | DHW Pipe Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Labor | DHW Pipe Insulation | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 Attic Ins. R-38****Components a2****Inspected****Comment** Insulate second floor attic 500 sq. ft. thur ceiling access that needs upgrade to TN. Field Guide Standard.Install R-38 to attic space blown in cellulose.Also upgrade attic access with insulation with insulation dams and W/S to hatch .☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|-------------------|---|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | Attic Insulation - Cellulose, Blown - R-38 | SqFt | 500 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Insulation | Attic Insulation - Cellulose, Blown - R-38 | SqFt | 500 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Labor | Labor to install attic access upgrade | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 2 | Construction Mate | Material to upgrade attic access with insulation dams and W/S | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 18018UE-1765

Alt. Client ID: Carter

Work Order (Bid Form)

Work Order Name: WO/18018UE-1765/1

Report Run On: 11/10/2011

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 5

Measure 5 Replace A/C**Components** ac1**Inspected**

Comment Replace Old window A/C with window heat pump sized to fit 700 sq. ft. for energy saving to home.

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|-----------------------|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Cooling Equipmen | Window A/C - | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Labor | Window A/C - | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Replace Htg. System****Components** h1**Inspected**

Comment Non-vented gas heater in use must replaced with vent gas wall heater to meet TN. Field Guide Standard. And Health of client. If unvented gas heater is not replaced this job is a walkaway due to unsafe condition with unvented gas heater in home.

☐

| # | Material / Labor | Description / Comment | Units | Qty | Estimated | | Actual | | |
|---|------------------|--|-------|-----|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Heating Equipmen | Space Heater - 10 kBtu/h Prop Existing, 38 - 54 kBtu/h Prop Post | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Labor | Space Heater - 10 kBtu/h Prop Existing, 38 - 54 kBtu/h Prop Post | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 18018UE-1765

Alt. Client ID: Carter

Work Order (Bid Form)

Work Order Name: WO/18018UE-1765/1

Report Run On: 11/10/2011

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 5

Measure 7 PressureRelief Piping Needed**Components****Inspected****Comment** Install to TN. Field Guide Standard 6 " from floor for safety to Client.☐

| # | Material / Labor | Description / Comment | Units | Estimated | | | Actual | | |
|---|-------------------|------------------------|-------|-----------|----------------------|----------------------|----------------------|----------------------|----------------------|
| | | | | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | Labor | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| 1 | Health and Safety | Pressure relief piping | Each | 1 | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Other Detail

| | | | | | | | | |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

Measure Sub Total: **Sub Total:** **Field Notes:****Work Order Grand Total:** **Grand Total:**

Client Name:

Client ID: 18018UE-1765

Alt. Client ID: Carter

Work Order (Bid Form)

Work Order Name: WO/18018UE-1765/1

Report Run On: 11/10/2011

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 5